

MOUNTING THE 70 LATHE ON A BENCH

The fixing holes necessary for the various beds and the opening for the belts are shown in the sketches below :

Bed for overhead drive 70-10.000



Bed for underneath drive 70-12.000



To prevent distortion of the profile of the bed on an insufficiently flat surface, the beds rest on three spherical washers 70-10.003. Two sheetmetal plates are supplied with the lathe. Placed on the bench, they prevent the washers from digging into the wood.

After mounting check with a rule whether the bed is clear of the plates and the bench.

